


Source: Leece-Neville Heavy Duty Systems Division - Arcade, NY USA  
Date: June 27, 2017  
Bulletin No: TSB-1022  
Models: 4834AA - 4950AA Series  
Subject: Subject

**This Technical Service Bulletin is intended to be used along with the TSB-1001 Recommended Wire Size Document.**

The follow wiring diagrams apply when wiring the 8RD2041 regulator with the 4834AA - 4950AA series alternators. See individual diagrams for actual models covered.




For recommended wire size refer to TSB-1001

Interface connector: Delphi Packard part number 12129600.


15 foot cable assembly is available per part number R049102681.

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers'; and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at:


Date: June 27, 2017  
Bulletin No: TSB-1022



For recommended wire size refer to TSB-1001  
Interface connector: Delphi Packard part number 12129600.  
15 foot cable assembly is available per part number R049102681.



For recommended wire size refer to TSB-1001  
Interface connector: Delphi Packard part number 12129600.  
15 foot cable assembly is available per part number R049102681.



For recommended wire size refer to TSB-1001  
Interface connector: Delphi Packard part number 12129600.  
15 foot cable assembly is available per part number R049102681.

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at: